

Detroit District P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6796 FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L01-53 Date: 13 JULY 2001

Waterway: LAKE HURON Location: MICHIGAN

CELRE-ET-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL HAMMOND BAY HARBOR

- 1. Condition surveys performed within the Federal navigation channel at Hammond Bay Harbor, Michigan during May 2001, indicate shoaling as shown on the back of this sheet.
- 2. Vessel operators should use caution when navigating within this area.
- 3. All inquiries should be addressed to CELRE-ET-OT-T and should refer to Notice to Navigation Interests No. L01-53. Internet address: http://huron.lre.usace.army.mil/OandM/o&m.html

RICHARD J. POLO, JR. Lieutenant Colonel, U.S. Army District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2001.



this map represents the results of surveys made on the dates indicated and can only be considered as inicating the general conditions existing at that time.

Surveys taken: MAY 2001

available depth below IGLD.

Soundings are in feet and are referred to Low Water Datum 577.5 ft. above Mean water level at Rimouski, Quebec, IGLD, 1985.

HAMMOND BAY HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 13 JULY 2001

U.S. Army Engineer District, Detroit

Ohammond.bmp

